



30mm face = 5889mm<sup>2</sup> of free air  
 120mm face = 23556mm<sup>2</sup> of free air  
 Airflow can be increased by leaving a continuous gap